B.R. No: 661/Date: 29/03/2014

Inspection report for the work of : Maintenance of borewell of Chikkasandra & Medarahalli, in Dasarahalli Zone

Chief Engineer
Dasarahalli Zone
BBMP, Banglore

Inspection Report

Name of Work	:	**Maintenance of borewell of Chikkasandra & Medarahalli, in Dasarahalli Zone**
Work Order	:	No. EE/DD/WO/ 157/13-14, Dated: 12/12/2013
Agency	:	S. Prakash
B.R. No & Dated	:	661/Date: 29/03/2014
Bill Amount	:	Rs. 1452513.00
Job Code	:	012-13-000040
P. Code	:	P1771

Date of Inspection : 10.7.2015

The Location of the Borewell is inspected by me along with Concerned Engineers and ascertained that as Borewell mantence works such as removing and refitting of the GI pipeline in the Borewell for repairing the Motor is carried out as shown in the photo's Enclosed.

ಮುಖ್ಯ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು